



ENRIQUE S. CAMARENA ELEMENTARY SCHOOL

August 10, 2012



Structural steel being installed on Building 100.



Overview from northwest corner of site.



Looking east at Building 200. (Building 100 is in background.)



Anchor bolts being installed for Building 300.

