



ENRIQUE S. CAMARENA ELEMENTARY SCHOOL

September 14, 2012



Building 100.



Structural steel being installed for Building 200.

Electrical/trash enclosure.



Pouring of slab completed for Building 400.



Grading for front parking lot. Tower of Building 100 is in left background.

